



## **Pinefield Road**

**Over time, the original service vehicle access barrier is now in the wrong place due to the success of the low level native scrub which has established behind it. It is still needed for mowing machinery and other service vehicles from time to time.**

**To accommodate this it is proposed that the bunding is extended to the wooded area and a new entrance formed in the middle, with a new barrier, ensuring the exclusion of unauthorised vehicles.**

