



## Options for Norwich Road

There is currently an informal entrance at the end of Norwich Road, which has been formed through the broken fence. It is narrow, muddy and the erosion has exposed the roots of a nearby tree.

The options here might be:

1. Leave as it is.
2. Formalise the entrance with the addition of steps and the installation of "Estate" railings and gate and a welcome sign, including information on the site. However, the steepness of the bank and the presence of the tree roots would prevent creating a suitable incline to allow disabled access at this point.
3. Repair the gap with a wire, stone and soil Gabion (which would become covered in Ivy and hidden), and estate railing fence. Thus preventing access at this point.